



CRIBAS | TABLAS PRINCIPALES TEJIDOS

	CALIBRE								
			3	6	8	10	12	14	16
	3/8" 9.5 mm	5/16" 7.9 mm	1/4" 6.4 mm	13/64" 5.0 mm	5/32" 4.0 mm	1/8" 3.3 mm	7.64" 2.7 mm	5/64" 2.1 mm	1/16" 1.6 mm
A Abierta 3" = 76 mm	79.0% 1018	82.0% 1018							
2 3/4" = 70 mm	77.4% 1018	80.6% 1018							
2 1/2" = 63.5 mm	75.6% 1018	79.0% 1018							
2" = 51 mm	79.0% 1018	74.8% 1018	79.0% 1018						
1 3/4" = 44 mm	67.8% 1018	71.9% 1018	76.6% 1018						
1 1/2" = 38 mm	64.0% 1018	68.5% 1018	73.4% 1018	78.0% 1018 1040					
1 1/4" = 32 mm	59.2% 1018	64.0% 1018	69.4% 1018	75.1% 1018 1040					
1" = 25 mm	59.2% 1018	58.0% 1018	64.0% 1018	70.4% 1018 1040	75.0% 1018 1040	77.6% 1018 1040			
7/8" = 22 mm		54.3% 1018	60.5% 1018	65.03% 1018 1040	70.0% 1018 1040	75.1% 1018 1040			
3/4" = 19 mm		49.8% 1018	56.3% 1018	63.4% 1018 1040	65.0% 1018 1040	71.8% 1018 1040	77.6% 1018 1040		
5/8" = 16 mm				58.5% 1018 1040	62.5% 1018 1040	67.6% 1018 1040	78.6% 1018 1040		
1/2" = 12.7 mm				52.2% 1018 1040	57.0% 1018 1040	62.0% 1018 1040	68.3% 1018 1040		
7/16" = 11 mm				50.0% 1018 1040	53.0% 1018 1040	58.4% 1018 1040	65.0% 1018 1040	71.5% 1018 1040	76.4% 1018 1040
3/8" = 9.5 mm				45.0% 1018 1040	50.0% 1018 1040	54.1% 1018 1040	61.0% 1018 1040	67.9% 1018 1040	73.3% 1018 1040
5/16" = 7.9 mm					45.0% 1018 1040	48.8% 1018 1040	56.0% 1018 1040	63.4% 1018 1040	69.3% 1018 1040
1/4" = 6.4 mm					40.0% 1018 1040	45.0% 1018 1040	49.6% 1018 1040	57.4% 1018 1040	63.8% 1018 1040
3/16" = 4.8 mm							41.1% 1018 1040	49.1% 1018 1040	56.0% 1018 1040
5/32" = 4 mm								40.8% 1018 1040	51.2% 1018 1040
1/8" = 3.3 mm									44.0% 1018 1040
3/32" = 2.5 mm								29.0% 1018 1040	36.0% 1018 1040

PRINCIPALES MATERIALES



Acero Negro
Tipo 1018 y 1040

Si la criba que necesitas no la encuentras en nuestras tablas, consúltanos y con toda seguridad podremos satisfacer tus necesidades.